

## BELANGRIJKE VEILIGHEIDSWAARSCHUWING

Qlima mobiele airconditioner  
PH 534  
EAN 8713508777344



### SPECIFICATIONS MOBILE AIRCONDITIONER Qlima

Model	PH 534
Cooling / Heating capacity *	3.2 kW / 2.5 kW
EE Class*	A
EER *	2.6
COP Class *	A+
COP*	2.7
Mains voltage	230 V ~ / 50 Hz / 1 Ph
Current	5.3 A
Power consumption in cooling mode	1.23 kW
Power consumption in heating mode	1.04 kW
Sound power level	65 dB(A)
Unit protection	IP X0
Pressure suction / discharge	12 / 23 (max. 23) bar
Refrigerant charge / GWP	R290 / 260 g / 3
CO <sub>2</sub> equivalent	0.001 tonnes
Net weight	31 kg
Serial number	AJ

\* conform EN 14511  
Distributed in Europe by PVG Holding B.V.,  
P.O. Box 96, 5340 AB Oss, The Netherlands, Qlima.com



Qlima PH 534  
Contains fluorinated greenhouse gases covered by the Kyoto Protocol.  
Refrigerant: R290: 260g / GWP: 3  
Hermetically sealed

Refrigerant leakage contributes to climate change. Refrigerant with lower global warming potential (GWP) would contribute less to global warming than a refrigerant with higher GWP, if leaked to the atmosphere.

PVG heeft ontdekt dat sommige van de PH 534 mobiele airconditioners een productiefout bevatten. Onder bepaalde omstandigheden kan dit leiden tot kortsluiting in het apparaat. In extreme gevallen, wanneer een niet-geaard stopcontact wordt gebruikt, kan hierdoor een steekvlam ontstaan. Wanneer vervolgens plastic onderdelen smelten, kan de rook die hierbij vrijkomt ernstige veiligheidsrisico's veroorzaken.

Heeft u dit product in uw bezit, **haal dan onmiddellijk de stekker uit het stopcontact en gebruik het apparaat niet meer**. Neem een foto van het informatielabel (zie afbeelding hierboven) en noteer het serienummer (beginnend met AJ of AI). Bewaar het apparaat vervolgens in een goed geventileerde kamer met een vloeroppervlak van minimaal 4 m<sup>2</sup>, en uit de buurt van bronnen van vuur of vonken.

Neem vervolgens contact op met PVG International, belt u hiervoor 0412-694 694 of mail naar [aftersales@pvg.eu](mailto:aftersales@pvg.eu) om uw product aan te melden. Wij zorgen er dan voor dat uw apparaat geïnspecteerd en, wanneer nodig, gerepareerd wordt.

Door de gevolgen van de COVID-19 uitbraak zijn we soms minder goed bereikbaar, of kan het wat langer duren alvorens u een reactie van ons ontvangt. Wij bieden hiervoor onze welgemeende excuses aan.